AS9102 First Article Inspection				
Form 1: Part Number Accountability				
1. Part Number	2. Part Name	3. Lot Number (or batch # if no S/N	4. Qty.	
	INSERT, SCREW THREAD), SAMPLE/12-8-2014	35,000	
5. Part Revision Level	6. Drawing Number	7. Drawing Revision Level	8. Additional Changes	
REV. 3	1032L0285	NEW		
9. Manufacturing Process I	Ref 10. Organization Name	11. Supplier Code	12. P.O. Number	
	HELICAL WIRE, INC.	0EE83		
13. Detail FAI	X Full F	AI X For Partial F	X For Partial FAI list Baseline Part Number & revision level	
Assembly FAI	Partial F			
Reason for Partial FAI				
a) If above part number is a detai				
b) If above part number is an assembly go to the "INDEX" section below. INDEX of part numbers or sub-assembly numbers required to make the assembly noted above.				
15. Part Number	16. Part Name	17. Part Serial Number		
 Signature indicates that all characteristics are accounted for, meet drawing requirements or are properly documented for disposition. 				
2) Also indicates if the FAI is complete per Section 5.4 X FAI Complete FAI Incomplete				
19. Signature		20. Date 12/8/2014		
21. Reviewed By	R.PERKINS	20. Date 12/8/2014		
23. Customer Approval	C. SALINAS	20. Date		
1032L0285-FORM 1-FAI December 2011				